INSPECTION CONDITIONS 206 E STEPHANSON STREET REPORTED BY PROSPECTOR HOME INSPECTIONS

SECTION	SIIR SECTION	Havadvava	LOCATION	ISSITE
FOUNDATION - STRUCTURE -				
EXTERIOR	GENERAL COMMENTS	2.2	2.2 Front exterior	Loose/soft EIFS Finish; mold
	FOUNDATIONS	2.4	2.4 Rearmost portion	Minor cracks
	GRADING & LANDSCAPE	2.6	2.6 Landscape	Animal infestation under slab
	2		183	Minor damage at various areas of
	EXTERIOR WALLS	2.8	2.8 Overall condition	penetration
	DOORS	2.13	2.13 Rear entry door	Deadbolt, no panic hardware
		2.14	2.14 Overhead door	Slide tab only for security
ROOFING SYSTEM	OVERHANGS/ROOF EDGE	3.7	Overhand	One damaged spot
	ATTIC	3.8	Stairs	No handrail
		200		Restricted air flow due to ceiling
			¥	insulation contacting the underside of
	VENTILATION	3.14 Rio	Ridge vents	the roof sheathing
		•		Need to extend downspots for water
	GUTTERS & DOWNSPOUTS	3.15	3.15 Downspouts	diversion
PLUMBING SYSTEM	HOT WATER SOURCE	4.15	Water heater	Manufactured in 2007
6	×			Check local fire department
	FIRE SPRINKLER SYSTEM	4.2		requirements
× ×				
ELECTRICAL	SMOKE ALARMS	5.19	5.19 Smoke alarms	None installed
AIR CONDITIONING &	Other statute concentration and the statute control of the statute c		New York Towns	
HEATI NG SYSTEM	COMPUTER ROOM	6.36	6.36 Air handler	May not be a permanently installed unit

INSPECTIO CONDITIONS 206 E STEPHENSON STREET REPORTED BY PROSPECTOR HOME INSPECTIONS

SECTION	SUB SECTION	PARAGRAPH	LOCATION	ISSUE
INTERIOR AREAS	WALLS	7.2	7.2 Front of building & additi Minor expansion cracks	Minor expansion cracks
				Damaged from condensation and not
	CEILINGS	7.3	7.3 Ceiling tiles	from leaks
	DOORS	7.6	7.6 Rear door	Should have panic hardware installed
	BATH AREAS	7.1	7.1 Men's room	Vent fan cover loose